SERVICE BULLETIN

KODAK X-OMAT Processor

Eastman Kodak Company, Health Imaging, Imaging Service Center, Rochester, New York 14650

SERVICE BULLETIN NO. 239

May 1996

3058 *KODAK X-OMAT* Multiloader 300
3059 *KODAK X-OMAT* 270 RA Processor
3198 *KODAK X-OMAT* 180 LPS Processor
3227 *KODAK X-OMAT* 180 LP Processor
3434 *KODAK X-OMAT* 3000 RA Processor

Publication Updates for the new TANK and Associated Parts Changes in the *KODAK X-OMAT* 180 LP and 180 LPS Processors

All *Kodak X-Omat* 180 LP Processors starting with serial number 3000 and *Kodak X-Omat* 180 LPS Processors starting with serial number 13,000 have the same new style TANK and improved WASH SYSTEM as the new *Kodak X-Omat* 3000 RA Processor. The new TANK and WASH SYSTEM are not meant to be retrofitted into existing Processors in the field. The following updated publications for the 180 LP and 180 LPS Processors cover these part changes as well as general updates to the publications.

Publication	Publication No.	Publication Date
Parts List	1C7842	Feb 1996 supersedes July 1995
Installation Instructions	1C7836	Feb 1996 supersedes July 1995
Diagrams	1C7841	Feb 1996 supersedes July 1995
Publication Change Notice for the Site Specifications for the *Kodak Ektascan* 2180 Laser Printer and the *Kodak X-Omat* 180 LP and 180 LPS Processors	8B7023	Feb 1996 updates Site Specification, 4B5476 dated Feb 1995

© Eastman Kodak Company

Publication	Publication No.	Publication Date
Publication Change Notice for the Adjustments and Replacements for the *Kodak X-Omat* 180 LP and 180 LPS Processors	8B7024	Feb 1996 updates Adjustments and Replacements, 1C7837 dated July 1995
Publication Change Notice for the Service Manual for the *Kodak X-Omat* 180 LP Sorter	8B7025	Feb 1996 updates the Service Manual, 1C7843 dated July 1995

Design Changes and Improvements on these Processors: 180LP and 180 LPS, 270 RA, and 270 RA in a Multiloader 300

New plastic SPROCKETS for the DRYER RACKS replace the old SPROCKETS that tended to corrode.

New SQUEEGEE ROLLERS for the DRYER RACKS are made of a high grade of stainless steel to better resist corrosion. They are installed with screws, which eliminates the E-RINGS that could corrode and break. The new SQUEEGEE ROLLERS are shipped with all the necessary hardware and instructions to install them in existing DRYER RACKS with the old style SQUEEGEE ROLLERS.

New Part	New Part No.	Old Part No.
Plastic SPROCKET	8B7109	914736
SQUEEGEE ROLLERS for the UPPER DRIVEN ROLLER	8B7110	1C0983
SQUEEGEE ROLLERS for the LOWER DRIVEN ROLLER	8B7111	1C0985

New FRONT EXIT ASSEMBLY Available for the 3000 RA Processor

A FRONT EXIT ASSEMBLY kit is now available to convert the 3000 RA Processor from TOP FILM EXIT to FRONT FILM EXIT. Installation time is approximately 2 hours. The kit, CAT No. 874-3890, can be ordered from Health Imaging Customer Service, 1-800-677-9933. Fax, 1-800-933-4840.

For More Information:

U.S. Distributors Contact:

Health Imaging

Customer Support Organization

1-800-336-4722

CES Personnel Contact:

Film Handling TAC

U.S.: 1-800-822-1414

Canada: 1-800-433-1414

International: 716-724-4675

Kodak and *X-Omat* are trademarks.